




106 Twin Terrace Way  
Spring Branch, Texas 78070-6288

Phone: 830-438-3808  
Email: sales@trans-heat.com  
Web: trans-heat.com

Romans 10:11 For whosoever believes on Him shall not be ashamed.



## ACCESSORIES



Accessories

CL-1 caution labels are used for identifying areas where heat trace is installed and are helpful for alerting operations personnel of potential shock hazards. CL-1 caution labels are to be affixed on insulating materials placed over heat trace. Recommended placement is between 10' and no more than 25' apart.

PS series pipe straps are used to secure connection kits via mounting brackets to pipes and other convenient appendages. PS series pipe straps are constructed of 201/301 stainless steel and have a 5/16" hex head for ease of installation.

The PTB power termination boot is for use with self-regulating cables only. It's an alternative to heat shrink and slides right over the conductors. The kit comes with a packet of silicone to provide a strong seal.

Example Configuration	PS-1	Weight
PTB	Power Termination Boot	0.8 oz.
PS <sup>1</sup>	1=1"-3" Pipe Size <sup>1</sup>	1.2 oz.
	2=2"-14" Pipe Size <sup>1</sup>	2.8 oz.
	3=3/4"-1" Pipe Size <sup>1</sup>	0.8 oz.
CL-1	Caution Labels (5/Pack)	1.0 oz.